

PARLIAMENT HILL ATHLETICS TRACK HAMPSTEAD HEATH  
PROGRESS PHOTOS

BURKE HUNTER ADAMS

02/08/23 – Heavy rainfall caused delay to track construction






PARLIAMENT HILL ATHLETICS TRACK HAMPSTEAD HEATH  
PROGRESS PHOTOS

BURKE HUNTER ADAMS

11/08/23 – Ground conditions and vehicle movement causing damage to existing track sub-base and surfacing







PARLIAMENT HILL ATHLETICS TRACK HAMPSTEAD HEATH  
PROGRESS PHOTOS

BURKE HUNTER ADAMS

17/08/23 – Continued issue with ground conditions under lighter vehicle loads





PARLIAMENT HILL ATHLETICS TRACK HAMPSTEAD HEATH  
PROGRESS PHOTOS

BURKE HUNTER ADAMS

23/08/23 – Track defects made good, additional reconstruction complete using lean concrete mix / mesh in areas.





PARLIAMENT HILL ATHLETICS TRACK HAMPSTEAD HEATH  
PROGRESS PHOTOS

BURKE HUNTER ADAMS

24/08/23 – Surfacing works mostly complete, floodlight bases excavated and re-enforcement cages being installed.

